



LABORATORY TEST REPORT

ULR - TC587522000002791F

Form / Format No : 32

Page 1 of 2

Issued To : LAMIFAB INDUSTRIES (Gujarat) Plot No.4702, 4703, 4704, 4705, 4604-4605, GIDC, Plastic Zone, Sarigam - 396155, Tal - Umergaon, Dist - Valsad, Gujarat State, India. Gujarat Kind Attn : --	Test Report No	100/02-2122/5077
	Date	08 Feb 2022
	Date of Start of Test	04 Feb 2022
	Date of Completion of Test	08 Feb 2022
	Customer Ref.No	Covering Letter
	Ref. Date	04 Feb 2022
	Sampling Plan	Sampling done by the party

Sample Description : One set of sample said to be HDPE Tarpaulin.

Test Results


Test done as per : IS 7903 : 2017

Sr No.	Test	CL.Ref	Unit	Requirement	Results Obtained	Remarks
1	Breaking Load Warp Weft	Table 1	N	Min. 1100 900	1538 1162	Complies
2	Grammage (Mass of finished tarpaulin)	Table 1	g/m ²	Min.250	250.03	Complies
3	Water Repellency (Cone test:Before ageing)	6.3.1	-	There shall be no leakage	No leakage was observed.	Complies
4	Water Proofness (Resistance to water penetration:Pressure head test:Before ageing)	6.3.1	-	Water does not leak through the tarpaulin	No leakage was observed.	Complies

Note : Tested as per IS 7903:2017.



TESTED BY



ASST./DY./JT. DIRECTOR



HEAD
LABORATORIES DIVISION

This report is for Private use only Not to be used for publicity or Litigation

Testing laboratories of Mumbai are certified by ISO 9001: 2015, NABL, BIS, Directorate General of Shipping and Directorate General of Civil Aviation, Govt. of India for specified tests.

Head Office:Plot E-2, Road No.*. MIDC Area, Andheri (East), Mumbai 400093

Tel:+91-22-2821 9803 / 6751 / 9469 28391506 28329623 28254631 Fax:+91-22-28328178 / 28375302 Email: rdiin@iip-in.com Website:



LABORATORY TEST REPORT

Test Report No. : 100/02-2122/5077

ULR - TC587522000002791F

Form / Format No : 32

Date : 08 Feb 2022

Page 2 of 2


General Remarks

1. This test report cannot be reproduced except in full, without written approval of the laboratory. This is not applicable when part report is given due to failure of the machine or test in progress.
2. Sampling done by the party. The test samples are submitted by the client. The sample descriptions provided in the test report are based on declaration by the party.
3. This report pertains to the submitted samples only.

----- End of Test Report -----



TESTED BY



ASST./DY./JT. DIRECTOR



HEAD
LABORATORIES DIVISION

This report is for Private use only Not to be used for publicity or Litigation

Testing laboratories of Mumbai are certified by ISO 9001: 2015, NABL, BIS, Directorate General of Shipping and
Directorate General of Civil Aviation, Govt. of India for specified tests.

Head Office:Plot E-2, Road No.*. MIDC Area, Andheri (East), Mumbai 400093

Tel:+91-22-2821 9803 / 6751 / 9469 28391506 28329623 28254631 Fax:+91-22-28328178 / 28375302 Email: rdiin@iip-in.com Website: